



U.S. Department
of Transportation

**Pipeline and
Hazardous Materials Safety
Administration**

12300 W Dakota Ave , Suite 110
Lakewood, CO 80228

SENT TO COMPLIANCE REGISTRY
Hardcopy ☐ Electronically ☒
of Copies 1 / Date 9-11-08

WARNING LETTER

CERTIFIED MAIL - RETURN RECEIPT REQUESTED

September 4, 2008

Mr. Perry Richards
General Manager
Questar Gas Management
1050 17th St
Denver, CO 80265

CPF 5-2008-5027W

Dear Mr Richards

On May 20, 2008, a representative of the Pipeline and Hazardous Materials Safety Administration (PHMSA), pursuant to Chapter 601 of 49 United States Code, inspected your Blacks Fork Line in Granger, Wyoming

As a result of the inspection, it appears that you have committed probable violations of the Pipeline Safety Regulations, Title 49, Code of Federal Regulations. The items inspected and the probable violations are

1. §195.420 Valve maintenance.

(b) Each operator shall, at intervals not exceeding 7 1/2 months, but at least twice each calendar year, inspect each mainline valve to determine that it is functioning properly.

The Main line valve inspections on the Blacks Fork Line were done once a year, not twice per year, not to exceed seven and one half (7-1/2) months for HVL Lines as required. This violation was discovered during the records inspection at the Granger, Wyoming facility.

2. §195.428 Overpressure safety devices and overfill protection systems

(a) Except as provided in paragraph (b) of this section, each operator shall, at intervals not exceeding 15 months, but at least once each calendar year, or in the case of pipelines used to carry highly volatile liquids, at intervals not to exceed 7½ months, but at least twice each calendar year, inspect and test each pressure limiting device, relief valve, pressure regulator, or other item of pressure control equipment to determine that it is functioning properly, is in good mechanical condition, and is adequate from the standpoint of capacity and reliability of operation for the service in which it is used.

The Overpressure Safety Devices tested on the Blacks Fork Line were done once a year, not twice per year, not to exceed seven and one half (7-1/2) months for HVL Lines as required. This violation was discovered during the records inspection at the Granger, Wyoming facility

Under 49 United States Code, § 60122, you are subject to a civil penalty not to exceed \$100,000 for each violation for each day the violation persists up to a maximum of \$1,000,000 for any related series of violations. We have reviewed the circumstances and supporting documents involved in this case, and have decided not to conduct additional enforcement action or penalty assessment proceedings at this time. We advise you to correct the items identified in this letter. Failure to do so will result in Questar Gas Management being subject to additional enforcement action.

No reply to this letter is required. If you choose to reply, in your correspondence please refer to **CPF 5-2008-5027W**. Be advised that all material you submit in response to this enforcement action is subject to being made publicly available. If you believe that any portion of your responsive material qualifies for confidential treatment under 5 U.S.C. 552(b), along with the complete original document you must provide a second copy of the document with the portions you believe qualify for confidential treatment redacted and an explanation of why you believe the redacted information qualifies for confidential treatment under 5 U.S.C. 552(b).

Sincerely,



Chris Hoidal

Director, Western Region

Pipeline and Hazardous Materials Safety Administration

cc PHP-60 Compliance Registry
PHP-500 J. Haddow (# 120732)